

## **Troll Flexifit Crampon Recall**

Technical Report: 12/04/02: Troll are recalling the following crampons:

T10 Flexfit

T12 Flexfit

T12 Fastfit

The current plastic components may exhibit impact brittleness at low temperatures, therefore crampons should be returned for these components to be replaced.

Please contact the retailer where the goods were purchased or contact Troll (now owned by HB) directly to be allocated a returns reference number:

[www.hbclimbing.com/contact.htm](http://www.hbclimbing.com/contact.htm)

Please do not return crampons without this reference number.

Troll apologise for any inconvenience and thank you for your co-operation in this matter.